

RECOMMENDED CLEANING OF YOUR SHOWER ENCLOSURE

The following chart shows the results of testing various bathroom cleaners on the anodic coating of bath enclosure aluminum parts. Parts were placed in a solution of each cleaning product and the results were recorded.

These tests were performed on Alumax, Coral, Efron and Craft finishes. The results were basically the same for each manufacturer; however the Alumax finish did exhibit less damage than competitor metal in some cases. There were no cases in which Alumax finish proved to be inferior to the competitor finishes.

PRODUCT	PH	DURATION OF EXPOSURE	EFFECT OF FINISH
Lime Away	1	XX	Destroyed
S.O.S Vinegar Glassworks	4	XXXXXXXXXXXXXXXXXXXXXX	Unaffected
Klean & Shine	7	XXXXXXXXXXXXXXXXXXXXXX	Unaffected
Glass Plus	9	XXXXXXXXXXXXXXXXXXXXXX	Unaffected
Scratch Guard	9.5	XXXXXXXXXXXXXXXXXXXXXX	Destroyed
Mr. Clean	11	XXXXXXXXXXXXXXXXXXXXXX	Destroyed
Windex	11	XXXXXXXXXX	Severe Damage
Direct	11.5	XXXXXXXXXXXXXXXXXXXXXX	Destroyed
Fantastik	12	XX	Diminished
Formula 409	12	XX	Severe Damage
Tough Act	13	XX	Destroyed
Tackle	13	XX	Destroyed
Dow Bathroom Cleaner	13	XX	Destroyed

5 10 14 24
 Min. Min. Hrs. Hrs.